



IMPORTANT SAFETY RECALL NOTICE REGARDING CERTAIN COLT MODERN SPORTING RIFLES

COLT'S MANUFACTURING COMPANY LLC ("COLT") has recently discovered a potential safety issue with certain Modern Sporting Rifles ("MSRs"). Colt is voluntarily initiating a recall to protect the safety of its customers because, under certain conditions, it is possible that some of these MSRs may discharge a second round when the trigger is released when there is a live round in the chamber.

Colt is committed to the highest standards of quality and customer satisfaction. In keeping with that commitment, during routine quality testing, Colt discovered that hammers that do not meet Colt's specifications were installed in certain MSRs that were manufactured beginning on March 5, 2021. The issue will be corrected by replacing the hammers in affected MSRs.

The recall only covers a portion of MSRs manufactured beginning on March 5, 2021, and includes the following models: AR15A4, CR6700A4, CR6920, CR6920-EPR, CR6920MPS-B, CR6921, CR6921-EPR, CR6933, CR6933-EPR, CR6960, LE6920-EPR, LE6920MPS-B, LE6920-OEM1, LE6920-OEM2, LE6920-R, LE6933-EPR, SP633784, LE6920SOCOM.

The following chart lists all the serial numbers for those models that may potentially be subject to the recall:

Model Marking	Serial Numbers
AR-15 A4	CAR022851 – CAR023250
CARBINE	CR036354 – CR099599
CARBINE	CR713001 – CR722100
M4 CARBINE	CR716801 – CR721500
M4A1 CARBINE	CR021580 – CR022024

To prevent the possibility of death or serious personal injury, Colt advises anyone who has purchased a Colt MSR since March 5, 2021 to stop using it immediately and visit ColtRepairMSR.com or call Customer Service at 1-800-971-3216 to see if your specific MSR is affected. Please note: Not all MSRs within the serial number range in the above chart are subject to this recall and this website offers easy, step-by-step instructions to determine if a particular MSR is affected.

Customer service agents will assist anyone who needs additional help. Our expert craftsmen are ready to upgrade all affected MSRs at our West Hartford, CT headquarters.