

# IMPORTANT SAFETY RECALL

## MR. STEAK™ Gas Grills

Model Nos. MS-4B-PG (four burner) and MS-5B-PG (five burner)



The regulator hose with an attached fuel gauge can melt if it comes in contact with the bottom of the grill's firebox, posing a fire hazard.

If your grill has a fuel gauge attached to the regulator hose and the fuel line is not attached to the side of the grill, stop using the grill and contact the MR. STEAK recall hotline to receive a free repair kit.



**833-677-8325 or 833-MRSTEAK from 8 a.m. to 6 p.m. ET Monday through Friday, or online at [mrsteak.com/repairpartskit](http://mrsteak.com/repairpartskit)**

Post Until: April 15, 2020

In cooperation with  
U.S. Consumer Product Safety Commission  
and Health Canada