



IMPORTANT SAFETY NOTICE

Textron Specialized Vehicles Inc. is voluntarily repairing, at no charge to customers, certain gas-powered Tracker Off Road vehicles to correct a potential fire hazard. This action applies to vehicles **manufactured from Nov. 1, 2018 to June 30, 2019**, with **serial numbers ranging from 3377720 to 3440924**. Affected models are pictured below.



Tracker LS2



Tracker LX4



Tracker LX6

Tracker Off Road Authorized Dealers are repairing affected vehicles free of charge.

If your vehicle is among those affected, stop using the vehicle immediately. Contact your Tracker Off Road Authorized Dealer today to schedule your free repair. Do not operate your vehicle until the repair is performed.

For more information, please call 706-792-5707.

This action is being taken in cooperation with the U.S. Consumer Product Safety Commission.
Post until Dec. 31, 2019.